






# The CDF II Silicon Detector Longevity and Performance

**Michelle Stancari**  
Fermi National Accelerator Laboratory  
(on behalf of the CDF Silicon group)



# Silicon Operations Group



# Things to watch in an aging detector

## Radiation damage to sensors:

- ▶ Will the depletion voltage eventually exceed the sensor breakdown voltage and/or power supply limits?
- ▶ Will the decreasing S/N ratio affect the physics analyses before underdepletion?

## Radiation damage to electronics:

- ▶ Power supplies, FIB readout modules in collision hall
- ▶ DOIM data transmitters in the bore

## Chip and sensor failure rates:


- ▶ No dramatic increase in failures with age

## ISL cooling system:

- ▶ Stable after 2007 and 2009 repairs



# CDF II Silicon Detectors



## Overview:

- ✓ Three components: L00, SVX-II, ISL
- ✓ 8 layers, 722k readout channels
- ✓ 3D hit information
- ✓ SVX3D chips


## SVX: Double sided silicon

Layers 0,1,3 (Hamamatsu)  $90^\circ$  strips

Layer 2+4 (Micron) small angled strips



**ISL:** Additional layers, Hamamatsu+Micron  
add **forward coverage**

**L00:** Single-sided, radiation hard sensors  
“Narrows” (SGS Thomson  
and 2 Micron) “Wides” (Hamamatsu)



# Depletion Voltage Measurements


- ▶ Measure collected charge for different bias voltages
- ▶ CDF defines depletion voltage,  $V_d$ , as the minimum voltage that collects 95% of the charge at the plateau



- ▶ Depletion Voltage as a function of integrated luminosity  
3<sup>rd</sup> order polynomial fit around the inversion point  
Linear fit to extrapolate to the future


# Depletion Voltage Projections

## Prediction for L00



Today's operating voltages



## Prediction for SVX-L0



Predictions for SVX-L1 show no danger of underdepletion before 20  $\text{fb}^{-1}$ .

# L00 depletion voltage measurement




Underdepletion is **not** instant death, but a slow process of decreasing efficiency!



A single L00 ladder was unintentionally underdepleted in 2007-08. Its efficiency was restored after a bias voltage increase from 95 to 150V.

# Signal/Noise Measurements

- ▶ Signal from  $J/\psi \rightarrow \mu^+ \mu^-$  tracks strip cluster charge
- ▶ Noise estimation from regular calibrations
- ▶ Extrapolations assume fully depleted sensors
- ▶ Studies in progress to understand the effect of decrease S/N on physics analyses for run 3 (see recent CDF talk to PAC)




# Ladder Failures and Challenges

Radiation damage in the sensors is not the only issue!


One ladder = chain of 4-14 readout chips (128 microstrips each chip)

Currently ~90% ladders integrated, ~80% good (< 1% error rate), ~10% bad with an average error rate of 10%

Great performance after 9 years of running



# Other Radiation Effects





- ▶ SEU requires FPGA and fuse replacement on FIBS (2/year)
- ▶ Power Supplies need replacement capacitors every  $5 \text{ fb}^{-1}$
- ▶ DOIM TX light output decreases linearly with radiation dose

# DOIM Longevity

- ▶ Dense Optical Interface Modules contain 9 edge-emitting laser diodes that transmit data from the bore to electronics outside the detector.
- ▶ These are solid state devices, and thus experience radiation damage, similar to the sensors.
- ▶ CDF note 6497 reports on beam tests which measured the decrease in output light intensity linear with total dose: **80±20% for 400 krad dose.**
- ▶ Integrated luminosity of  $20 \text{ fb}^{-1} \Rightarrow \sim 1 \text{ Mrad}$  to the DOIMs.
- ▶ 2010 Shutdown work: measured light intensity for  $\sim 10\%$  of detector (900 numbers!). Status is good.
- ▶ Light-amplifying circuit is being built to recover a few ladders with initial light below specs that is now below the receiver threshold of 50  $\mu\text{W}$ .

# Light Intensity Measurements

- ▶ Measured 10% of detector at receiver input.
- ▶ Receiver threshold is 30-50  $\mu\text{W}$ .
- ▶ Weakest bit in each ladder is critical
- ▶ Predicting the future is not trivial



# Summary and Conclusions

- ▶ The CDF Run II silicon detector is in extremely good health after 9 years of operation.
- ▶ The innermost layers have long progressed through inversion and exhibit consistent post-inversion behavior.
- ▶ The measured DOIM light intensities are well above the receiver thresholds. We will monitor the loss rate in the future.
- ▶ Stable performance will continue through the end of run II.

# Backup Slides





# Chip Accounting - SVX

## Common failure modes:


**Detector** includes port cards, junction cards, cables, and the sensors themselves.

**Optical** is bit errors from the internal DOIM data transmitters

**Jumper** is SVX3D chip failures due to wire bond resonances

**AVDD2** is a SVX3D chip failure mode caused by thermal cycles


**Other SVX3D** includes all other chip failure modes



# ISL Cooling System: The Saga of 2007

## The Problem


- ◆ In 2007, bad vacuum in ISL indicates presence of leaks. Eventually, east side bad enough to interfere with detector operations.
- ◆ Found high acidity in coolant, **pH = 2**
- ◆ Formic acid had formed out of the glycol/water mixture (after warming up during the 2006 shutdown)
- ◆ Corrosion affected vulnerable parts (Al-alloys welding, brass e-valves)






# ISL Cooling System: The Saga of 2007

## The Repair

- ◆ Internal walls of pipes were probed using boroscopes and catheters (~1 m inside CDF detector)
  - Port Card manifold-pipe junctions **were coated with epoxy**
  - Brass e-valves were replaced (mounted on CDF detector)
- ◆ The ISL coolant was replaced with deionized water
  - Expanded monitoring of **pH and conductivity**
  - Frequent replacement of deionizer (DI) resin filters






## Current status of ISL Cooling

- ◆ Running, no serious incidents
- ◆ Good and stable flows
  - ◆ ISL CCE1 is stable but lower than perfect
- ◆ Good and stable sub-atmospheric pressures
- ◆ pH measured weekly from coolant samples
- ◆ Low conductivity  $< 2 \mu\text{S}/\text{cm}$
- ◆ Maintenance during each shutdown to improve hermeticity
- ◆ Chillers running well,

◆ New air-cooled backup chiller for power outages


# Chip accounting - ISL



- ▶ No jumper failures for ISL because readout happens only after L2 accept
- ▶ No AVDD2 failures because of warmer temperature than SVX
- ▶ Sensor recovery after JC pushes (disconnected cables)
- ▶ Long history of cooling problems
  - ▶ 2003 – unblocked cooling lines
  - ▶ 2007 – major leak repaired


# Measured Radiation Field

- Radiation field measured with TLDs outside the silicon volume in 2002-2003.
- NIMA514 188 (2003)
- Bias current evolution 2002-2004 consistent with this radiation dose



# Depletion Voltage Projections

## Prediction for LI – phi side



## Prediction for LI – z side

