



## Status of Vessel Drawing Submittal by CVIP

Inner Vessel drawings complete and nearly all approved.

Outer vessel drawings under review

Final manufacturing procedure is approved, but there are some final additions.



## BNL Pulsed Magnet Manufacturing Status Sept 8 2004






Photo taken by Dave Rakos at Everson 09-08-04. Kapton layer spaced at every eighth turn relieves axial tension in the layers near the cooling channels. First Layer, Coil Segment#2




Kapton arc sections inserted between every eighth turn on those layers that face the cooling channels



Faint indication of silver soldered scarf joint



Silver Solder Joint Tensile Test



Load Displacement plot of Silver Solder Joint.