



Pictures of Lab G window sparks




Outside view of the west window sparks.




Same as before





Cooper grains left inside due the sparks



Iris spark damage.